

Jacksonville FL New Roof

Client: National Property Mgt Co.

Summary: Failed roof was preventing our client from conveying the property. The roof had been left so long it had rotted through to all the ceiling joists. We had to remove and replace the entire roof, all sheathing, and all structural support joists and studs. We then replaced all rotted fascia boards.

Scope:

- **New Roof**
- **New Structural Support for roof**
- **New Fascia and trim**
- **Included all permits and city sign off**



Rotted Sheathing & Joists



NEW Sheathing & Joists



Before New Roof



After New Roof

