

Cleveland OH – Crime Scene Clean up and New Bathroom floor

Client: SFR Investor

Summary: Crime scene clean up on bathroom floor and walls. We then completely renovated the bathroom to bring it back to better than original condition.

**Scope:
Crime Scene Clean up
Demolished existing bathroom.
Installed new sub floor
Installed new LVP floor
Installed new toilet
Installed new pedestal sink
New plumbing**

