

Fitchburg MA Project

Client: REO Realtor Listing

Summary: Local Realtor wanted to list this property for a quick sale in "as is" condition. This was a hoarder home with extreme debris, exterior overgrowth and health hazards on the interior. We cleaned up the property over a three-day period and allowed the Realtor to get the listing online as quickly as possible.

Scope:

- Trash out (100+ yards)
- Interior Feces Removal
- Bleach Clean Entire House
- Rekey all doors, lockbox
- Winterization
- Initial Yard Maintenance
- Tree Removal
- Tree trimming
- Shrub Trimming



Before Exterior Photos



After Exterior



Tree removal before & after




Tree trimming before & after



Trash out before



Trash out before



Trash out after



Trash out after

